CIVIL QUALITY CONSULTANTS & ENGINEERS
ISO 9001:2015 Certified & NABL Accredited Laboratory as per ISO/IEC - 17025-2017

Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Name of Work : Construction of Arch and Providing Interlocking Tiles In Front of Sai Baba Temple And Construction of RCC Roof for Ramp Near Ganesha Temple in Ward No 17 & Widening and Improvements to Road From BEL Circle to Mattikere Fly Over, BBMP, Bangalore

Name of Client	:	**Executive Engineer,** R R Nagar Division, BBMP, Bangalore.
Contractor/Agency	:	**M/s SKS Infrastructure Pvt Ltd,** Bangalore.
Total Cost	:	Rs. 75.14 Lakhs
Date of Inspection	:	20.07.2022
Reference number	:	EE/RRND/Wo.No/000062/2021-22
Status of Bill	:	3rd and Final Bill
In the Presence of	:	(a) **Assistant Engineer,** Ward No.17, BBMP, Bangalore.
	:	(b) **Mr. Mohan G,** Engineer M/S Civil Quality Consultants and Engineers, Bangalore

Compliance Report

Sl.No	Description of the Item	Unit	Qty		Comments / observations
1	Providing and constructing Precast concrete solid blocks with compressive strenght not less	Sqm	74.68	:	Work done upto the billed Quantity and Quality is satisfactory.
2	Providing and constructing granite / trap / basalt size stone masonry in basement with	Cum	2	:	Work done upto the billed Quantity and Quality is satisfactory.
3	Providing and laying in position plain cement concrete of mix 1:2:4 with OPC cement @	Cum	8.31	:	Work done upto the billed Quantity and Quality is satisfactory.

CIVIL QUALITY CONSULTANTS & ENGINEERS ★ Bangalore

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-560
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Scanned with CamScanner

CIVIL QUALITY CONSULTANTS & ENGINEERS

ISO 9001:2015 Certified & NABL Accredited Laboratory as per ISO/IEC - 17025-2017

Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Sl.No	Description of the Item	Unit	Qty		Comments / observations
4	Providing 18mm thick cement plaster in single coat with cement mortor 1:3, to brick masonry	Sqm	64.48	:	Work done upto the billed Quantity and Quality is satisfactory.
5	Providing 12mm thick cement plaster in single coat with cement mortor 1:4, to ceiling including	Sqm	617.90	:	Work done upto the billed Quantity and Quality is satisfactory.
6	Providing and laying flooring using prepolished water cut/gang saw 19 mm thick Granite laid	Sqm	19.71	:	Work done upto the billed Quantity and Quality is satisfactory.
7	Providing vitrified tiles 1000 x 1000mm /800x1200mm of approved make, shade and size	Sqm	40.38	:	Work done upto the billed Quantity and Quality is satisfactory.
8	KSRB 14.15-1: Providing marble slab flooring 20mm thick with edges of slab machine cut, for	Sqm	3.6	:	Work done upto the billed Quantity and Quality is satisfactory.
9	Providing and fixing in position 12mm thick plaster of paris (gypsum anhydrous) for ceiling	Sqm	66.49	:	Work done upto the billed Quantity and Quality is satisfactory.
10	KSRB 15-5.1: Providing rough plastering 15mm thick in single coat with cement mortor 1:4, to	Sqm	16.20	:	Work done upto the billed Quantity and Quality is satisfactory.
11	KSRB 14.4 : Providing and laying flooring and steps fine dressed granite stone slabs 40mm thick	Sqm	50	:	Work done upto the billed Quantity and Quality is satisfactory.
12	Providing & fixing of glazed 2 Track-2 Panel Sliding Windows made out of multi Chamered	Sqm	1.45	:	Work done upto the billed Quantity and Quality is satisfactory.
13	Providing and fixing M.S.grill work for windows and ventilators weighing 21 kg/sqm using M.S.	Kg	31.5	:	Work done upto the billed Quantity and Quality is satisfactory.
14	Providing and laying integral cement based waterproofing treatment including preparation	Sqm	38.89	:	Work done upto the billed Quantity and Quality is satisfactory.
15	Providing and laying in position Yelahanka tiles of size 250 x 250mm of approved quality and	Sqm	38.89	:	Work done upto the billed Quantity and Quality is satisfactory.

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-560
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Scanned with CamScanner

Sl.No	Description of the Item	Unit	Qty		Comments / observations
16	OPEN Conduit System:Supplying following size heavy guage PVC conduit pipe confirming to IS	Each	449.8	:	Work done upto the billed Quantity and Quality is satisfactory.
17	Supply of LED floodlight luminaire with pressure die cast aluminium housing body for	Each	60	:	Work done upto the billed Quantity and Quality is satisfactory.
18	Supplying capacitor type ceiling fan complete with down rod blades, shackle, canopies etc., for	Each	6	:	Work done upto the billed Quantity and Quality is satisfactory.
19	Fixing halogen/ metal halide/ SVL/ IL / LED flood light fitting over existing pole/ wall	Each	4	:	Work done upto the billed Quantity and Quality is satisfactory.
20	Providing and fixing white vitreous china clay, flat back wash basin of size 550x400mm with a	Nos	2	:	Work done upto the billed Quantity and Quality is satisfactory.
21	Providing and fixing in position brass bib cock of approved quality 20mm nominal bore	Nos	4	:	Work done upto the billed Quantity and Quality is satisfactory.
22	Providing and fixing C.P. brass towel rail 600 mm length, 20mm dia with C.P. brackets, fixed to	Unit	4	:	Work done upto the billed Quantity and Quality is satisfactory.
23	Providing and fixing in position brass stop cock of approved quality 15mm nominal bore	Each	4	:	Work done upto the billed Quantity and Quality is satisfactory.
24	Providing and fixing CI Nahani Trap of approved make conforming to ISI specifications	Each	5	:	Work done upto the billed Quantity and Quality is satisfactory.
25	Earth work excavation for foundation of buildings, water supply, sanitary line and electrical	Cum	86.72	:	Work done upto the billed Quantity and Quality is satisfactory.
26	Providing and fixing chlorinated poly veny chloride (CPVC) pipes conforming to IS 15778, having	Mtr	75	:	Work done upto the billed Quantity and Quality is satisfactory.
27	Providing and fixing chlorinated poly veny chloride (CPVC) pipes conforming to IS 15778, having	Mtr	65	:	Work done upto the billed Quantity and Quality is satisfactory.

Scanned with CamScanner

CIVIL QUALITY CONSULTANTS & ENGINEERS
ISO 9001:2015 Certified & NABL Accredited Laboratory as per ISO/IEC - 17025-2017
Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Sl.No	Description of the Item	Unit	Qty		Comments / observations
28	Providing and fixing chlorinated poly veny chloride (CPVC) pipes conforming to IS 15778, having	Mtr	65	:	Work done upto the billed Quantity and Quality is satisfactory.
29	KSRB 13-6.2.6: Providing and fixing in position brass gate valve with C.I. wheel of approved	Nos	4	:	Work done upto the billed Quantity and Quality is satisfactory.
30	KSRB 13-6 4.1: providing and fixing in position brass ball valve high or low pressure with plastic	Each	4	:	Work done upto the billed Quantity and Quality is satisfactory.
31	Supppying water storage tanks made of virgin polymer (LLDPE) with two layers outer black of	Ltr	2000	:	Work done upto the billed Quantity and Quality is satisfactory.
32	Providing and fixing to wall, ceiling and floor unplasticised PVC	Mtr	60	:	Work done upto the billed Quantity and Quality is satisfactory.
33	KSRB 12-8.1 : Constructing brick masonry inspection chamber 455x610mm, and 450mm depth,	Nos	4	:	Work done upto the billed Quantity and Quality is satisfactory.
34	Providing and fixing to wall, ceiling and floor, medium density polyethylene pipes	Mtr	25	:	Work done upto the billed Quantity and Quality is satisfactory.
35	KSRB 2-2.1: Earthwork excavation for foundation of buildings, culverts, water supply,	Cum	608.96	:	Work done upto the billed Quantity and Quality is satisfactory.
36	KSRB - 4.9.2: Providing TMT steel reinforcement for R.C.C work including straightening,	Tonne	6.6	:	Work done upto the billed Quantity and Quality is satisfactory.
37	KSRRB 300- Scarifying the surface and dressing KSRRB 300-44: Scarifying top bituminous	Sqm	501.3	:	Work done upto the billed Quantity and Quality is satisfactory.
38	KSRRB M 400-17, Providing, laying, spreading and compacting graded stone aggregate to wet mix	Cum	148.74	:	Work done upto the billed Quantity and Quality is satisfactory.
39	Royal Bench: Made out of Sadrahallii grey stone with hand support with machine cutting top	Nos	12		Work done upto the billed Quantity and Quality is satisfactory.

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-560 05
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Scanned with CamScanner

CIVIL QUALITY CONSULTANTS & ENGINEERS
ISO 9001:2015 Certified & NABL Accredited Laboratory as per ISO/IEC - 17025-2017

Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Sl.No	Description of the Item	Unit	Qty		Comments / observations
40	KSRB 4.2.2 : Providing and laying in position Reinforced cement concrete of Design mix M20 with OPC cement @ 320kgs, with	Cum	120.42	:	Work done upto the billed Quantity and Quality is satisfactory.
41	KSRB 14.6-1 : Providing and laying heavy duty cobble stones 75mm thick interlock pavers, using cement and course sand for	Sqm	640	:	Work done upto the billed Quantity and Quality is satisfactory.
42	Providing and fixing granite name board fixed in cement morter to wall."The board shall be fixed as per the drawing and at the place	Sqm	1	:	Work done upto the billed Quantity and Quality is satisfactory.
43	KSRRB M100-1 & M100-4.1. Conveying by Loading and unloading of moorum/debris. Placing tipper at loading point,	Cum	426.16	:	Work done upto the billed Quantity and Quality is satisfactory.
44	KSRRB M400-6.2: Construction of granular sub case by providing close graded material, spreading in uniform layers with motors	Cum	172.43	:	Work done upto the billed Quantity and Quality is satisfactory.
45	KSRRB M600-1: Construction of dry lean cement concrete mix CC1:5:10 with OPC cement @ 160kg, with 25mm and down size	Cum	172.43	:	Work done upto the billed Quantity and Quality is satisfactory.
46	KSRRB M600-2: Cement concrete pavement : construction of unreinforced, dowel jointed, plaint cement concrete pavement	Cum	172.43	:	Work done upto the billed Quantity and Quality is satisfactory.
47	Vaccum De- writing with vaccum pump and suction mat and compaction with skin floater clubbed with floating disc	Sqm	1149.5	:	Work done upto the billed Quantity and Quality is satisfactory.

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-560 05
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Scanned with CamScanner